Legend

- New Path Tee/Green to fairway
- Existing concrete path
- New Path adjacent to fairway
- New drainage swale
- New mounds
- New hollows & pits

Notes

1. All bunkers to be reviewed in terms of drainage and treatment.
2. Macro drainage system should be reviewed across the course to improve playability and recovery.
3. Irrigation system to be audited and recomenedations made to upgrade/replace to improve water useage into the future.

Mollymook Golf Course

PROGRAMMED Turnpoint

Course Improvements Plan v3

Date: April 2015

Scale. 1:1500 @ A0

0 50 100 150 200 250